

Hoorn, November 29, 2017

**Concerns:** *Official statement Safety Alert Holland Lift T210 Scissor Lifts*

*Holland Lift International BV, in cooperation with the International Powered Access Federation, voluntarily issues the following safety alert with respect to the Holland Lift T210 scissor lifts, built before January 2016.*

*On the 26st of October Holland Lift was notified by one of their customers about welding cracks in a T210 scissor lift in the UK. Based on that message Holland Lift decided to recall this specific scissor lift for further inspection, analysis and repair in the Netherlands.*


*On the basis of the information at that time available, and a first assessment on other T210 scissor lifts of the same batch, there was no increased risk for the safety of the personnel using this type of equipment (apart from any general safety risk related to working with AWP's).*

*No accidents have been reported; however, in the interest of safety, Holland Lift has decided to voluntarily issue a safety alert to all stakeholders to prevent any unrest, and as a precautionary measure, Holland Lift decided to inspect all T210 lifts, built before 2016. Most of these scissor lifts have been inspected and up to now we have not found any critical problems.*

*When all inspections are finalized Holland Lift will inform the related stakeholders of the outcome and/or any required actions.*

*Safety is, and will always be, top priority. Holland Lift will never make concessions towards safety.*

*We hope to have informed you sufficiently, but please do not hesitate to contact us if you have any further questions or comments.*



*Rik van Sonsbeek*

*Managing Director a.i.*  
**HOLLAND LIFT INTERNATIONAL**

**Holland Lift International bv**

Anodeweg 1 • NL-1627 LJ Hoorn • The Netherlands • t: +31 (0) 229 285 555 • f: +31 (0) 229 285 550 • [www.hollandlift.com](http://www.hollandlift.com)  
KvK 36041120 • Bank NL52ABNA0501302220 • BIC ABNANL2A • BTW B01 NL801510806B01